

MODEL: ComColor 90xx, 70xx & 30XX

DATE 4 February., 2010

Data Category Field Modification Trouble Shooting General Information Safety Advice**Proceeding Grade**

- Action ASAP
 Action as given
 Action if required
 Refer in need

Parts Compatibility

- Compatible
 Conditionally Compatible
 Not Compatible
 Old Obsolete

Handling of Modified Parts

- Free of Charge
 Conditionally Chargeable
 Chargeable

Our Ref.

SUBJECT: Modification to improve Belt Platen (BP) paper feed**[Brief]**

1. The BP belt has been changed to improve the A4 size portrait paper feeding.
2. Due to the change of the BP belt, the setting value of the Transfer Belt Fan should be adjusted using Test mode.

1. BP Transfer Belt:

The pattern of holes on the Transfer belt has been changed to improve paper feeding.

**(NEW TYPE)****050-75056-054****(OLD TYPE)****050-19001-000****2. Transfer Belt Fan Set (TM1809):**

The transfer belt fan setting (TEST MODE 1809) should be adjusted depending on which type of BP belt is used.

1. Machines that have the old type BP Belt:

Please set Test mode setting of TM1809 at "60".

2. Machines that have the new type BP Belt:

Please set Test mode setting of TM1809 at "100".

Attached:

[Application Tips]

If you have the paper feed problems with curled A4 size portrait paper, please replace the BP unit with the new type.

[Note]

1. Required Test mode adjustment when replacing the BP belt:

This machine has a counter to compensate for the action of belt rotation and it revises the data automatically. So, it is required to reset the following data when replacing the belt or BP unit.

TM 1540: B-STRETCH DATA CLEAR (Initialize the belt stretch data)

TM1447: BELT MAINT CNT RESET (Maintenance Count Reset when replacing the belt)

2. Modification of PLATEN

The shape of PLATEN (050-19018) also has been changed twice as below.

First) Several Mylar sheets were added to the PLATEN to make the openings on it appropriate.

Second) The holes on the PLATEN were changed.

[Newly registered Part]

050-74007-688

BELT PLATEN

050-75056-054

TRANSFER BELT SU

[Application serial Number]

For New type Transfer Belt & PLATEN with Mylar

CC9050	Not applicable
CC7050	Not applicable
CC3050	33370007
CC7010	33460009
CC3010	33470015

[Application serial Number]

For New type PLATEN with New type Transfer Belt

CC9050	33350088, 0090 & over
CC7050	33360071
CC3050	33370027
CC7010	33460066
CC3010	33470037, 0041-0043, 0045-0065, 0067, 0069 & over

Attached: